

Doc. No. : PDN210901
Date : Sep 17, 2021

To : Dear Valued Customers

Product Discontinuance Notice

Subject : Products discontinue.			
Parts Affected :			
Part No.	Package	Part No.	Package
CDBFR00340-HF	1005/SOD-323F	CDBFR0540-HF	1005/SOD-323F
CDBFR03100-HF	1005/SOD-323F	CDBFR40-HF	1005/SOD-323F
CDBFR0130-HF	1005/SOD-323F	CDBFR43-HF	1005/SOD-323F
CDBFR0130L-HF	1005/SOD-323F	CDBFR54-HF	1005/SOD-323F
CDBFR0140L-HF	1005/SOD-323F	CDBFR70-HF	1005/SOD-323F
CDBFR0230-HF	1005/SOD-323F	CPDFR12V-HF	1005/SOD-323F
CDBFR0240-HF	1005/SOD-323F	CPDFR24V-HF	1005/SOD-323F
CDBFR0520-HF	1005/SOD-323F	CPDFR5V0-HF	1005/SOD-323F
CDBFR0520L-HF	1005/SOD-323F	CPDFR5V0U-HF	1005/SOD-323F
		CDBM140LR-HF	SOD-123F
Reason for Discontinuance :			
Due to low demand, the part listed below will be discontinued.			
Alternative Products :			
Please contact sales person or manufacturer's representative.			
Effective Date : Mar 10, 2022			
R&D Dept. Signature :		QA Dept. Signature :	
			