

 Not Actual Photo YIC International Co., Limited.	BA5838FM-E2 Hersteller-Teilenummer: BA5838FM-E2 Hersteller / Marke: LAPIS Semiconductor Teil der Beschreibung: IC MOTOR DRIVER 28SOP RoHs Status: Bleifrei / RoHS-konform Lagerzustand: New original, 1483 pcs Stock Available. Liefern von: Hong Kong Versandweg: DHL/Fedex/TNT/UPS/EMS
Image may be representation. See specs for product details.	

Spezifikationen

Teilenummer	BA5838FM-E2
Hersteller	LAPIS Semiconductor
Beschreibung	IC MOTOR DRIVER 28SOP
Kategorie	Integrierte Schaltungen (ICs) > PMIC-Motor-Treiber,
Teilstatus	1483 pcs Stock
Serie	*
Serie	-
RoHs Status	Lead free / RoHS Compliant
Bedingung	New Original Stock
Garantie	100% Perfect Functions
Vorlaufzeit	2-3days after payment.
Zahlung	PayPal / Telegraphic Transfer / Western Union
Versand per	DHL / Fedex / UPS
Hafen	HongKong
Anfrage-E-Mail	Info@YIC-Electronics.com

--

Sie können auch interessiert

sein:  Not Actual Photo YIC International Co., Limited. BA5836FP-FE2 ROHM BA5836FP-FE2 ROHM	 BA5835FP IC ROHM ROHM HSOP30	 BA5837FM-E2 Rohm Semiconductor IC MOTOR DRIVER 28SOP	 Not Actual Photo YIC International Co., Limited. BA5838FM ROHM BA5838FM ROHM
 BA5839FP-E2 Rohm Semiconductor IC MOTOR DRIVER SMD	 Not Actual Photo YIC International Co., Limited. BA5839FP ROHM BA5839FP ROHM	 Not Actual Photo YIC International Co., Limited. BA5840FM ROHM ROHM SOP28	 BA5840FM-E2 ROHM ROHM HSOP28

BA5838FM-E2 Zugehöriges

Mehr

Suchbegriffe	Suchbegriffe	Suchbegriffe	Suchbegriffe	Suchbegriffe
BA5838FM-E2 Lapiss Semiconductor	BA5838FM-E2 Datenblatt	BA5838FM-E2-Datenblätter	BA5838FM-E2 PDF	LAPIS Semiconductor BA5838FM-E2
BA5838FM-E2 Electronic	BA5838FM-E2-Komponenten	BA5838FM-E2-Verteiler	BA5838FM-E2-Bild	BA5838FM-E2-Teil
BA5838FM-E2 Preis	BA5838FM-E2 Hersteller	BA5838FM-E2 Bild	BA5838FM-E2 Aktie	BA5838FM-E2 Inventar
BA5838FM-E2 Neu	BA5838FM-E2 Original	BA5838FM-E2 garantiert	BA5838FM-E2 RFQ	BA5838FM-E2 Online bestellen